

# 2018 BOND IMPROVEMENTS\*



## Arvada Articulation Area

	Build new facility on same property	Expand with addition	Remodel building interior	Additions/renovations for programs	Growth accommodations	Remove modular buildings	Security camera & lock updates	Secure entries & office locations	New, more secure exterior doors	More secure & energy-efficient windows	Update existing technology	Landscaping & field improvements	Update interior paint, wall-coverings	Update electrical wiring & increase capacity	Update HVAC, plumbing & piping	Repair & update exterior finish	New paint to protect exterior	Commercial kitchen improvements	Parking lot & sidewalk improvements	Replace old playground equipment	Replace old furniture	Replace old carpet & floor tile	Replace movable partitions	Replace old sinks, cabinets & shelving	Replace interior lighting with LEDs	Replace worn roofing
Arvada High		●	●	●			●	●		●	●		●				●		●		●	●		●	●	●
Arvada K-8			●	●			●	●		●				●							●		●		●	●
Fitzmorris Elementary							●	●		●			●					●		●	●	●		●	●	●
Foster Elementary		●	●		●		●	●	●	●				●	●					●	●	●		●	●	●
Hackberry Hill Elementary							●	●		●			●	●			●	●	●	●			●		●	●
Lawrence Elementary			●				●	●		●		●	●	●				●	●		●		●	●		●
North Arvada Middle				●			●	●		●	●			●				●	●		●	●		●	●	●
Peck Elementary			●				●	●	●	●				●				●		●	●	●		●	●	●
Secret Elementary							●	●	●	●		●	●	●			●	●		●	●		●	●		●
Swanson Elementary					●		●	●		●			●						●	●	●		●	●	●	●
Thomson Elementary							●	●		●			●	●					●	●	●	●		●	●	●

\*Based on 2018 Capital Improvement Plan. Subject to project scope.

### Foster Elementary School Improvements

- Expand facility with an addition.
- Remodel of building interior.
- Remove modular buildings.
- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- Update existing technology for student learning.
- New, more secure exterior doors.
- New, more secure & energy-efficient windows.
- Update old electrical wiring, panels & increase capacity.
- Update old heating & cooling equipment, plumbing fixtures & piping.
- Replace:
  - Old playground equipment;
  - Interior lighting with energy-efficient LEDs;
  - Old carpet & floor tile;
  - Worn roofing; &
  - Old ceilings.



Age of Facility: 65 years (built in 1953)  
Square Footage: 42,486

Enrollment: 506

**BUILDING  
CONDITION:  
POOR**

**FCI: 41.3%**

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

Good: less than 10%  
Fair: 11% to 30%  
Poor: greater than 30%.

Estimated cost of proposed improvements: \$5,949,807. Subject to change per final project scope.