

# 2018 BOND IMPROVEMENTS\*



## Pomona Articulation Area

	Build new facility on same property	Expand with addition	Remodel building interior	Additions/renovators for programs	Growth accommodations	Remove modular buildings	Security camera & lock updates	Secure entries & office locations	New, more secure exterior doors	More secure & energy-efficient windows	Landscaping & field improvements	Update interior paint, wall-coverings	Update electrical wiring & increase capacity	Update HVAC, plumbing & piping	Repair & update exterior finish	New paint to protect exterior	Commercial kitchen improvements	Parking lot & sidewalk improvements	Replace old playground improvements	Replace old playground equipment	Replace old furniture	Replace old carpet & floor tile	Replace movable partitions	Replace old sinks, cabinets & shelving	Replace interior lighting with LEDs	Replace worn roofing			
Little Elementary							•	•		•		•	•	•						•		•	•	•		•	•	•	
Moore Middle							•	•	•	•		•	•	•							•				•				
Parr Elementary							•	•	•			•									•		•	•	•	•			
Pomona High		•	•	•			•	•	•	•	•	•	•	•	•	•					•		•	•	•		•	•	•
Warder Elementary							•	•		•			•											•	•	•			
Weber Elementary							•	•		•			•								•		•		•	•	•		

\*Based on 2018 Capital Improvement Plan. Subject to project scope.

### Moore Middle School Improvements

- Update old security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- New, more secure exterior doors.
- New, more secure & energy-efficient windows.
- Update existing technology for student learning.
- Update interior paint, wall-coverings.
- Update old electrical wiring, panels & increase security door hardware.
- Update old heating & cooling equipment, plumbing fixtures & piping.
- Replace:
  - Old lockers;
  - Old library furniture;
  - Interior lighting with energy-efficient LEDs; &
  - Old carpet & floor tile.



Age of Facility: 40 years (built in 1978)  
Square Footage: 83,756

Enrollment: 424

**BUILDING  
CONDITION:  
FAIR**

**FCI: 24.1%**

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

Good: less than 10%  
Fair: 11% to 30%  
Poor: greater than 30%.

Estimated cost of proposed improvements: \$2,163,362. Subject to change per final project scope.